

## Peugeot 5008 - 2010-2017 Our Ref HO506

2 variations available, please take time to consider which of the 2 most suits your requirements.



## I: BACK

## Row 2 seats slid as far back to the tailgate

The 3<sup>rd</sup> row foot well covers must be down to prevent heavy loads putting tension onto the liner over the recessed foot well

These will prevent the use of the 2 tie down "D" rings positioned under the cover.



I: FORWARD Row 2 seats slid as far forward to the front of the vehicle

The 3<sup>rd</sup> row foot well covers must be down to prevent heavy loads putting tension onto the liner over the recessed foot well

The 2 tie down "D" rings are left exposed. These are sometimes used vith dog guards or load retaining nets.