

BMW 2 SERIES ACTIVE – 2014 to 2021

Our ref: H0596

Question 1 – Nearside plastic pocket identification

H0596-PLA



AVAILABLE

With plastic storage insert on
boot side



Plastic storage insert remains
exposed

H0596-PLANO



AVAILABLE

No plastic storage insert on
boot side



NEXT PAGE



Question 2 – Seats slide position guide

H0596-SEBK

AVAILABLE 

Rear seats are slid as far back to the tailgate as possible



H0596-SEFW

AVAILABLE 

Rear seats are slid as far forward to the driver as possible



H0596-SEFIX

AVAILABLE 

Rear seats do not slide



Seat uppers must be in the most reclined rake position

