




Land Rover Discovery Sport - 2015 Onwards

Our ref: H0597

Question 1 - Vehicle Identification Guide






When the seats are most upright there is a void between the seat upper and

Note: this is the only suitable version for the P300e

SEREC AVAILABLE Rear seat backs reclined



When the seats are most reclined there is no void between the seat upper and the plastic molding

Note: NOT suitable version for the P300e

The Rear Seats must be slid as far BACK to the tailgate

The rear seats (Row 2) slide – the Boot liner only suits these seats slid as far back to the tailgate











RCS AVAILABLE

With recess in boot side


Rightside has this large recess in the panel







Rightside has plastic vent panel OR net (boot liner skims over net)





04/04/2024 | V.2 Page. 2