



Skoda Rapid Spaceback - 2013 to 2019

Our ref: H0745

Vehicle Identification Guide

FNO



Visible protrusions on boot corners







FIN



NOT AVAILABLE

False floor in (raised or lowered)

- Handle on false floor
- Plastic pockets on both sides



False floor raised



False floor lowered

10/02/2020 | v. 01 Page. 1