

## KIA Stonic - 2017 Onwards

Our ref: H0780

### Question 1 - Vehicle Identification Guide

#### H0780 - FRSD



AVAILABLE

#### False floor raised

The additional false floor is raised to the highest level



If you look under the false floor you can see this plastic moulding that supports it



#### H0780 - FLOW



NOT AVAILABLE

#### False floor lowered

The additional false floor is lowered to the lowest level (smaller section angled)



Next page



## KIA Stonic - 2017 Onwards

Our ref: H0780

### Question 1 - Vehicle Identification Guide

#### H0780 - FOUT



AVAILABLE

#### False floor removed

The additional false floor has been removed from the car and stored elsewhere



Visible seat hinge



Plastic moulding to support false floor



#### H0780 - FNO



NOT AVAILABLE

#### No false floor

The vehicle does not have an additional false floor and there are no plastic mouldings to support it.



Visible seat hinge



NO plastic moulding



If you are looking for this version, please contact [sales@hatchbag.co.uk](mailto:sales@hatchbag.co.uk)